



Procedure Execution Report

OPERATIONAL RECORD – SINGLE EXECUTION

REPORT NO.
EXECUTION ID
GENERATED

SAMPLE-EXR-001
900001
13/09/2026 14:00

STEPS EXECUTED	SUCCESS RATE	TOTAL TIME	PHOTOS	RATING	
8 / 9	89%	00h:02m:12s	0	—	FAILED

1 IDENTIFICATION

PROCEDURE Replacing servomotor 1		PROCEDURE ID 2336	TYPE Maintenance
PRODUCT SO-101	SERIAL NUMBER DEMO-UNIT-001	LOCATION Example workshop	EXECUTION TYPE Private
OPERATOR Sample operator	STARTED 13/09/2026 11:00	COMPLETED 13/09/2026 11:02	DURATION 00h:02m:12s

2 STEP CHECKLIST

#	STEP	TIME	STATUS	PHOTO EVIDENCE
1	Unscrew the Initial Set of Screws	00:24	EXECUTED	— no photo
2	Unscrew the Remaining Screws	00:20	EXECUTED	— no photo
3	Remove the Moving Jaw	00:12	EXECUTED	— no photo
4	Remove the wiring on the servomotor	00:10	EXECUTED	— no photo
5	Replace the servomotor	00:16	EXECUTED	— no photo
6	Wire the new servomotr	00:12	EXECUTED	— no photo
7	Install the Moving Jaw	00:18	EXECUTED	— no photo
8	Screw the Moving Jaw	00:20	EXECUTED	— no photo
9	Screw the Moving Jaw Sample: final step not completed.	—	NOT EXECUTED	— no photo

3 OPERATOR COMMENT

FICTIONAL EXECUTION FOR KIT PREVIEW. The final step is not recorded as executed. No physical work, inspection, photo evidence or approval is claimed.

4 SIGN-OFF

PERFORMED BY	REVIEWED BY	QUALITY APPROVAL
Sample operator 13/09/2026	 Date	 Date

Template source: TwinWorks execution-report/pdf.ts (0336e2a)